



COURSE.	DISTANCE.	REMARKS.
This Sectim. Survey was postponed by Deputy W ^m E Cox till Oct 26. when commenced Survey of same. Commenced at $E\frac{1}{4}$ S Section 7. - 4-6.		

North	39.50	S & on Section 6	Three North
"	4000	E $\frac{1}{4}$	" "
,	100.82	NE	" 4

I found that this was right after projecting him ~~that~~
from NE on Section 7.

met June 24. 20.19 N¹⁴ NE

40 38 18 $\frac{1}{4}$

6374 $\lambda^{\prime\prime}$

87/4 m G

362 863 1

South. from N.W.S. 6 7074 SE cor Sec 1. - 6-7 22 units met

1967 9874 SWCw Dec 6-6-6

This line. angles from S E S 12. 6-7. it is evident from original returns at E
Section 12. Still plain to be seen, that this is an original line as now by
Government Surveyors. Squibb. make corner still further South. by measuring from
E $\frac{1}{4}$ Sec 12. which is evidently as now.

Elst from Sir. G. 4742 5¹/4

8742 88 cm sec 4-4-4

Corners Established.	Monument.	Bearing Trees.	Diameter in Inches.	Course.	Links Distant.
SE	Stake	Cottonwood	4	1V 32 $\frac{3}{4}$ E	175
E $\frac{1}{4}$ SE	Stake	Pest in ground	4	most	10
E $\frac{1}{4}$	Stone	Pest in gro	3 feet long even with degree	10 most	
E $\frac{1}{4}$ NE	Stake	Maple	4	1Y 59 $\frac{3}{4}$ W	83 $\frac{1}{2}$
W $\frac{1}{4}$	Stake	Maple	20	8 21 $\frac{3}{4}$ E	29
Hickory					
SW	Drain tile	Stone		East	50
Stake in center					
W $\frac{1}{4}$ NW	Stake	Maple	20	N 21 $\frac{1}{2}$ W	119
N $\frac{1}{4}$ NE	Stone	Stone	X	South	50
N $\frac{1}{4}$ NW	in center of Bridge at most End. Even with Bumister				
W $\frac{1}{4}$ SE	Stone	No trunings	.in front grounds		
S $\frac{1}{4}$ NW	Stake	on East Edge of ditch.			
Center $\frac{1}{4}$	Stone	No trunings			
Center NE	Stone	No trunings			

By F.M. Parker May 1899
7 1/4 Limestone already set corals maple about zone